

Intra-Company Communication

NEW YORK WORLD'S FAIR

June 19, 1964

TO: Gayle Warnock  
Bill Hersey

SUBJECT: Moisture Mess on Ride Cars

Today at 6:15 p.m. I checked on the condition of the ride cars and found that considerable water had dripped on the East Ride cars. After the felt strips had gone across them, the hoods, windshields and rear decks were a mess. As you know, the humidity was very high.

To get the cars clean, we recruited more Allied men, transferred the two from the other track -- so we had six men cleaning the surfaces. They did a good job.

It was my understanding several days ago that corrective steps had been taken by installing drip pans at the trouble spots. The area supervisor today said he was of the opinion that the drip pans had been installed but had filled and run over. I am sure the humidity will get worse from now on. So, we should make sure that we are equipped to handle the problem.

I would suggest that Lou Columbus be requested to review the matter and take the necessary action in an effort to preclude further recurrences.

*DR*

David G. Dowling

DGD:lda

cc: T. L. Bewick, Jr.

L. Columbus